IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No	7,675,187 B2
Patent Issue Date	March 9, 2010
Application Serial No	10/577,577
Filing Date	October 5, 2004
Assignee	PowerSys, LLC.
Inventorship	Douglas Alan Koeneman, et al.
Attorney's Docket No	
Title: Power Generation Systems and Methods of Generating Power	

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR APPLICANT MISTAKES & PTO MISTAKES (37 C.F.R. 1.322(a) and 1.323)

To:

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

ATTN:

Decision and Certificate of Correction

Branch of the Patent Issue Division

From:

D. Brent Kenady (Tel. 509-624-4276; Fax 509-838-3424)

Wells St. John P.S.

601 W. First Avenue, Suite 1300

Spokane, WA 99201-3828

Sir/Madam:

It is hereby requested that a Certificate of Correction be issued with respect to Patent No. 7,675,187 B2, granted March 9, 2010, in accordance with the Certificate of Correction form attached hereto in duplicate.

It is noted that errors appear in this patent of a typographical nature of character, as more fully described below. The errors occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 7,675,187 B2

APPLICATION NO.: 10/577,577

DATED : March 9, 2010

INVENTOR(S): Douglas Alan Koeneman, Edward Woods

It is certified that errors appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 4, line 14 - Replace "devise" with --device--

Col. 8, line 39 – Replace "is illustrated Components of" with --is illustrated. Components of--

Col. 12, line 44 – Replace "unshaped" with --u-shaped--

Col. 15, line 53 - Replace "Bios" with --BIOS--

Col. 16, line 35 – Remove "It should be understood that all the schematic"

Mailing Address of Sender:

D. Brent Kenady Wells St. John P.S. 601 West First Avenue, Suite 1300 Spokane, WA 99201-3828

The other errors listed on the Certificate of Correction form were apparently incurred through the fault of the PTO as will be disclosed by the records of files in the Office.

Attached hereto is Form PTO-1050.

The exact page and line number where the error occurs in the application file are:

Page 5, line 14;

Page 11, line 11;

Page 16, line 33;

Page 21, line 7; and

Page 22, line 6.

The \$100 fee for filing this certificate of correction is hereby being paid via EFS Web.

Respectfully submitted,

By:

D. Brent Kenady Reg. No. 40,045